


## Safety Electrical Point Inspection



### 20A Junction Box

- » Cable & Connector  
Burnt Out



### Heater Switch

- » Cracked
- » Rusty